


# Sensor value report

Report date: 18.11.2022 12.30.00 - 19.11.2022 12.30.00

Asset: VDW Repair Centre loggers



| Node           | Sensor            | Unit | Min value | Max value | Avg value | Latest measurement | Latest value | State |
|----------------|-------------------|------|-----------|-----------|-----------|--------------------|--------------|-------|
| B01 - Sensor 1 | Ext Temperature 1 | °C   | 6         | 7.4       | 6.145     | 1.12.2022 6.28.14  | 14.5         |       |