


# Sensor value report

Report date: 29.11.2023 8.00.00 - 30.11.2023 8.00.00

Asset: VDW Repair Centre GPRS Gateway TGG Tel: +316 57105258



● last measurement less than 10 measurement intervals before     
 ● last measurement more than 10 measurement intervals before     
 ● no data for last measurement before

Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 4	Ext Temperature 4	°C	0.9	5	2.293	7.12.2023 19.32.24	-34.2	<span style="color: green;">●</span>