


# Sensor value report

Report date: 26.1.2024 10.30.00 - 27.1.2024 10.30.00

Asset: VDW Repair Centre GPRS Gateway TGG Tel: +316 57105258



- last measurement less than 10 measurement intervals before
- last measurement more than 10 measurement intervals before
- no data for last measurement before

Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 4	Ext Temperature 4	°C	1.8	9.3	4.526	21.2.2024 13.37.27	2.7	●