


# Sensor value report

Report date: 11.4.2024 14.00.00 - 16.4.2024 13.00.00

Asset: VDW Repair Centre GPRS Gateway TGG Tel: +316 57105258



- last measurement less than 10 measurement intervals before
- last measurement more than 10 measurement intervals before
- no data for last measurement before

Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 2	Ext Temperature 2	°C	2.3	17.4	3.945	17.4.2024 9.02.15	16.9	●