


# Sensor value report

Report date: 4.4.2024 16.00.00 - 8.4.2024 16.00.00

Asset: VDW Repair Centre GPRS Gateway TGG Tel: +316 57105258



- last measurement less than 10 measurement intervals before
- last measurement more than 10 measurement intervals before
- no data for last measurement before

Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 4	Ext Temperature 4	°C	-25.8	-8.7	-20.198	17.4.2024 9.27.15	17.9	●

Getest op -25°C en -20°C