


# Sensor value report

Report date: 27.6.2025 11.00.00 - 30.6.2025 16.30.00

Asset: VDW - Repair Centre GPRS Gateway TGG Tel: +316 57105258



| Node           | Sensor            | Unit | Min value | Max value | Avg value | Latest measurement | Latest value | State |
|----------------|-------------------|------|-----------|-----------|-----------|--------------------|--------------|-------|
| B02 - Sensor 3 | Ext Temperature 3 | °C   | -21.9     | 22.3      | -16.993   | 2.7.2025 21.29.23  | 26.2         |       |