


Sensor value report

Report date: 9.7.2025 9.00.00 - 21.7.2025 9.25.00

Asset: VDW - Repair Centre GPRS Gateway TGG Tel: +316 57105258



Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 1	Ext Temperature 1	°C	-23.2	21.3	-20.304	13.8.2025 16.51.27	25.2	